



## Test Report.

No. CANMLC1409706601

Date: 25 Jun 2014

Page 1 of 3.

NEW TECH BUILDING CC

NEW TECH BUILDING CC REG NO 1923/011466/23 PO BOX 1 TALL VIEW 6839 SOUTH AFRICA

The following sample(s) was/were submitted and identified on behalf of the clients as : Non asbestos calciums silicate board.

SGS Job No. : GZCCM140606614 - GZ  
Date of Sample Received : 19 Jun 2014.  
Testing Period : 19 Jun 2014 - 25 Jun 2014  
Test Requested : Selected test(s) as requested by client.  
Test Method : Please refer to next page(s).  
Test Results : Please refer to next page(s).

Signed for and on behalf of  
SGS-CSTC Ltd.

*Yan*

Yan Lee  
Approved Signatory



This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Documents.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.  
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: [CN.Doccheck@sgs.com](mailto:CN.Doccheck@sgs.com)

198 Kezhu Road, Sciencetech Park Guangzhou Economic & Technology Development District, Guangzhou, China 510663 t (86-20) 82155555 f (86-20) 82075113 www.sgsgroup.com.cn  
中国·广州·经济技术开发区科学城科珠路198号 邮编: 510663 t (86-20) 82155555 f (86-20) 82075113 e [sgs.china@sgs.com](mailto:sgs.china@sgs.com)

## Test Report.

No. CANMLC1409706601

Date: 25 Jun 2014

Page 2 of 3.

Test Results :.

### Test Part Description :

Specimen No.      SGS Sample ID.      Description.

SN1.              CAN14-097074.001      Gray board.

Remarks :.

- (1) 1 mg/kg = 1 ppm = 0.0001%
- (2) MDL = Method Detection Limit
- (3) ND = Not Detected ( < MDL )
- (4) "-" = Not Regulated

### Asbestos.

Test Method : With reference to NIOSH 9000:1994 and ISO 22262-1:2012, Analysis was performed by PLM and XRD..

Test Item(s)	CAS NO.	Unit.	MDL.	001.
Chrysotile.	012001-29-5.	% (m/m).	1	Negative
Amosite.	012172-73-5.	% (m/m).	1	Negative
Crocidolite.	012001-28-4.	% (m/m).	1	Negative
Anthophyllite.	077536-67-5.	% (m/m).	1	Negative
Tremolite.	077536-68-6.	% (m/m).	1	Negative
Actinolite.	077536-66-4.	% (m/m).	1	Negative

Notes :.

- (1) Negative means the absence of asbestos, Positive means the presence of asbestos.


## Test Report.

No. CANMLC1409706601

Date: 25 Jun 2014

Page 3 of 3.

Sample photo:



SGS authenticate the photo on original report only

\*\*\* End of Report \*\*\*